

I	MEMBER OF MORRIS GROUP INTERNATIONAL POST OFFICE BOX 3237 MONTGOMERY, ALABAMA 36109-0237 (USA) TEL: 334-277-8520 FAX: 888-377-7818 www.jrsmith.com MEMBER OF: MEMBER OF:				LOCATION							
	ROOF-CEPTOR® INDIRECT WASTE DRAIN											
DRAWING NUMBER	7 1/4"(185) TOP - MEDIUM DEPTH RECEPTORS Conforms to ASME A112.6.7/CSA B79.7											
SIZE												
SCALE:	☐ Fig. 3960C CAULK OUTLET ☐ Fig. 3960Y NO-HUB OUTLET ☐ Fig. 3960T THREADED OUTLET											
DATE:	9-19-85											
APPROVED BY:	JD											
CHECKED BY:	JD											
DRAWN BY:	PJ											
FIGURE NUMBER	3960											
WE CAN ASSUME NO RESPONSIBILITY FOR USE OF SUPERSEDED OR VOID DATA												
▲ This Dimension to Internal Stop of Speedi-Set® Gasket recommended deck openings: with suffix -R - 9"(230) less suffix -R - 7 3/4"(195) <table border="1" style="width: 100%; font-size: 0.8em;"> <tr> <th>A SIZE</th> <th>02 (50)</th> <th>03 (75)</th> <th>04 (100)</th> </tr> <tr> <td>B</td> <td colspan="3"> 5 1/2(140) for Caulk, NO-HUB and Speedi-Set®. 4 1/4(110) for Threaded </td> </tr> </table>					A SIZE	02 (50)	03 (75)	04 (100)	B	5 1/2(140) for Caulk, NO-HUB and Speedi-Set®. 4 1/4(110) for Threaded		
A SIZE	02 (50)	03 (75)	04 (100)									
B	5 1/2(140) for Caulk, NO-HUB and Speedi-Set®. 4 1/4(110) for Threaded											
REGULARLY FURNISHED: Duco Cast Iron Receptor with Solid Water Dam and Secured Cast Iron Dome Bottom Strainer. VARIATIONS: Extension -E L Speedi-Set® Service Weight LXH Speedi-Set® Extra Heavy Roof Sump Receiver -R Underdeck Clamp -UDC Roof Deck Plate - RDP OPTIONAL MATERIALS: <input style="width: 20px; height: 15px; margin-right: 5px;" type="checkbox"/> All Galvanized -G												
NOTE: Dimensions shown in parentheses are in millimeters.												
REV.	DATE	DESCRIPTION	BY	CKD. BY								
	5-8-25 4-19-24 7-26-23 3-13-23	Added RDP Option Added ASME Note Removed Function Added ® to Speedi-Set	JJT HS HS KK	BW BW CL CL								
		WEIGHT POUNDS	VOLUME CUBIC FEET									
		FIGURE NUMBER										
		3960										



WARNING: Cancer and Reproductive Harm - www.P65Warnings.ca.gov